

OIR: 2526/120

24 September 2025

Tēnā koe

Request for Information under the Local Government Official Information and Meetings Act 1987 (the Act) (the LGOIMA)

Thank you for your email of **17 September 2025** requesting the following information in relation to the Kaitawa flying fox:

#### A copy of the safety report for the frayed wire

The frayed wire is one observation tabled when the flying fox was assessed as part of the wider safety and condition assessment of the Kaitawa playspace. A copy of the playspace assessment, which includes the flying fox as a component, and a high-level flying fox specific report are attached.

Ngā mihi,

**Brendan Owens** 

Group Manager Customer and Community Kaiwhakahaere Rōpū - Kiritaki me te Hapori

Please note that any information provided in response to your request may be published on the Council website, with our ersonal details removed.



# Katawa Reserve Flying Fox







Future Landscapes Ltd

To: Kapiti Coast District Council

Date: 10 th September 2025

Re: Flying Fox – Kaitawa Reserve

#### **Background**

Future Landscapes was engaged to conduct an annual playground inspection of the playground at Kaitawa Reserve. The inspection reviewed the play items against the NZS Playground Standard NZS 5828:2015 and risk assessed it using the Risk Matrix below. (supplied by The Play Inspection Company UK).

The flying fox is located in Kaitawa Reserve to one side of the reserve and estimated to be over 30 years in age. The flying fox is situated on the slope of the reserve and traverses over a creek with rocks located on either side. The end of the run finishes at the creek bed on a slope. To take the seat to the start of the flying fox one has to cross over the stream. There is no impact surface along the run which is over 1m in height from the seat at several places.



#### **Findings**

- The cable traverses over a creek at the end of the run which has rocks located on the bank and within it resulting in a hard object within the falling space. There is no impact properties in the event of a fall, which could result in a head injury if falling into the creek bed.
- To take the trolley back to the start, a child has to pull the trolley over the creek.
- The cable is fraying and needs to be replaced.
- The seat is not secure on the chain and needs to be secured.

### Assumptions

People regularly use the flying fox which crosses over a creek, evident in the wear on the far bank. The finish of the run is over the creek, and to take the trolley back to the start a user has to cross the creek. In the event a person was to fall, there is the possibility they could fall onto a rock or log submerged in the creek which may result in a potential head injury or death.

The risk calculation was carried out as follows:

Likelihood - 4 Severity - 5 Risk – 20

The findings indicate a potential risk factor of High.

# 

Risk Assessment Matrix

quipment has been assessed to the following standards where relevan S EN 1176 Parts 1-11 (Playground equipment and surfacing)

3S EN 14974 (Facilities for users of roller sports equipme 3S EN 15312 (Free access multi-sports equipment)

BS EN 16899 (Parkour Equipment) BS EN 16630 (Outdoor Fitness Equipment).



#### Conclusion

The flying fox is a play item which takes the user over the creek. There is no impact surface under the fall zone of the cable. In the event of an accident there is the potential for serious harm. The flying fox is situated on council land and as such there is a duty of care.

#### Recommendation

- Seek legal advice with regard to Duty of Care under the Occupiers Liability Act, or
- Remove the flying fox in its current location and replace with a compliant flying fox in another part of the reserve where impact properties can be addressed.

Kind Regards

Philippa Bollond

**RPII Level 3 Inspector** 



Photos

Rocks within creek bed and on creek edge













# **Annual Inspection**

Kapiti Coast District Council

Kaitawa Reserve



#### **Risk Assessment Matrix**

			Scores in the report are multiplication factors of Likelihood x Severity					
				Severity>>				
Likelihood	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
				Very Low	Low	Moderate	High	Very High
FUTURE LANDSCAPES			1	2	3	4	5	
			No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality	
				Severity>>				

Note 1: The total risk scores included within our reports are a multipication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

## Kaitawa Reserve

Inspection Ref: 2798963 Site Ref: 62420

Inspected: 22-August-2025 - 08:01 by Philippa Bollond (RPII Annual Inspector)

Risk Assessment: 20 High Risk



#### Location:

The site is partially overlooked by properties in the local community Disabled Access:

Some accessible features; an area that presents difficulties to the majority of people with disabilities but in favourable circumstances and certainly in partnership can be accessed.



#### 1 - Very Low Risk

Item: Safety surface
Manufacturer: Unknown

Surface Type: Rubber Tiles

Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: Yes

Life Expectancy: 3 - 5 Years

Total Findings: 1

Finding 1

This item is satisfactory - no work required -



# •

### 2 - Very Low Risk

Item:2 Bay (2 Flat, 2 Cradle)Manufacturer:Playground People

Surface Type: Rubber Tiles

Item Quantity: 2
Equipment Compliance: Yes
Surface Area Compliance: Yes

Life Expectancy: >10 Years

Total Findings: 1

#### Finding 1

The item has missing component(s) - Consider replacing missing components



#### 🧌 8 - Low Risk

Item: Climbing Frame

Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 2 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

**Total Findings:** 1

#### Finding 1

There is algae or moss on the surface of the equipment - Clean and treat appropriately



#### 1 - Very Low Risk

Item: Low Rotator

Manufacturer: Playground People

Surface Type: Woodchip


Item Quantity: 2 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

**Total Findings:** 

#### Finding 1

This item is satisfactory - no work required -



### 1 - Very Low Risk

Item: Free Standing Slide Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 2 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Life Expectancy: >10 Years

**Total Findings:** 1

#### Finding 1

This item is satisfactory - no work required -



### 1 - Very Low Risk

Item: Low Rotator

Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 2 **Equipment Compliance:** Yes Surface Area Compliance: Yes

5 -10 Years Life Expectancy:

**Total Findings:** 

#### Finding 1

This item is satisfactory - no work required -





#### 6 - Low Risk

Four Way Springer Item: Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 2 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

**Total Findings:** 1



There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required



#### 10 - Low Risk

**Balance Beam** Item: Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 2 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

**Total Findings:** 

Finding 1

#### Finding 2

There is some evidence of rot in the timber - Monitor for any Bolts show signs of rust - inspect and replace bolts, screws

further deterioration and replace as required and or nails as required





# f

#### 6 - Low Risk

Item: Log Walk

Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 2



There is some evidence of rot in the timber - Monitor for any

further deterioration and replace as required



#### Finding 2

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint



#### 10 - Low Risk

Item: Basket Swing - Type 1

Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 2
Equipment Compliance: Yes
Surface Area Compliance: Yes

Life Expectancy: >10 Years

Total Findings: 1

Finding 1

Bolts show signs of rust - inspect and replace bolts, screws and or nails as required



#### 📆 6 - Low Risk

Misc Springer Item:

Manufacturer: Playground People

Surface Type: Woodchip

Item Quantity: 2 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

**Total Findings:** 1

#### Finding 1

The paintwork on the spring has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint



#### 1 - Very Low Risk

Item: Safety surface

Manufacturer: Unknown Surface Type: Woodchip

Item Quantity: 1

**Equipment Compliance:** N/A Surface Area Compliance: Yes

Life Expectancy: 3 - 5 Years

**Total Findings:** 1

#### Finding 1

This item is satisfactory - no work required -



# ] 1 - Very Low Risk

Item: Treated Pine Sleepers

Manufacturer: Unknown
Surface Type: Woodchip

Item Quantity: 3
Equipment Compliance: N/A
Surface Area Compliance: N/A

Life Expectancy: 5 -10 Years

Total Findings: 1

#### Finding 1

This item is satisfactory - no work required -



### 20 - High Risk

Item: Cable Runway

Manufacturer: Unknown

Surface Type: Compacted Earth

Item Quantity: 3
Equipment Compliance: No
Surface Area Compliance: No

Life Expectancy: 3 - 5 Years

Total Findings: 6



#### Finding 1

Protruding wires - Secure protrusion

#### Finding 2

We recommend that the main cable is thoroughly inspected at least once every 2 years this; will involve either removing the cable or gaining access by ladders and/or steps to inspect for damage or internal rusting, this will help to ensure the continued safe use of the equipment - Inspect cable every 24 months

#### Finding 3

The rocks forms a hard object within the falling space of the equipment in contravention of the requirements of NZ 5828:2015 Part 1 - Relocate runaway so not over the stream

#### Finding 4

Seat not secured on chain - Secure seat so it cannot move up the chain

#### Finding 5

An impact absorbing surface is recommended for this item of equipment - Provide an appropriate impact absorbing surface

#### Finding 6

The chain openings are in excess of 8.6mm as recommended by NZ 5828:2015 - Monitor use and replace with compliant chains when swings needs replacing

# **Findings information**



Item: Swings - 2 Bay (2 Flat, 2 Cradle)

Manufacturer: Playground People

Risk Level: V - Very Low Risk
Surface: Rubber Tiles





Finding: The item has missing component(s)

Action: Consider replacing missing components

### 8 - Low Risk (Finding 1)

Item:Activity Equipment - Climbing FrameRisk Level:L - Low RiskManufacturer:Playground PeopleSurface:Woodchip





Finding: There is algae or moss on the surface of the equipment

Action: Clean and treat appropriately



#### 6 - Low Risk (Finding 1)

Item:Rocking Equipment - Four Way SpringerRisk Level:L - Low RiskManufacturer:Playground PeopleSurface:Woodchip



Finding: There is some evidence of rot in the timber



Action: Monitor for any further deterioration and replace as required

# •

#### 6 - Low Risk (Finding 1)

 Item:
 Activity Equipment - Balance Beam
 Risk Level:
 L - Low Risk

 Manufacturer:
 Playground People
 Surface:
 Woodchip



Finding: There is some evidence of rot in the timber



Action: Monitor for any further deterioration and replace as required



### 10 - Low Risk (Finding 2)

Item:Activity Equipment - Balance BeamRisk Level:L - Low RiskManufacturer:Playground PeopleSurface:Woodchip



Finding: Bolts show signs of rust

Action: inspect and replace bolts, screws and or nails as required

# •

#### 6 - Low Risk (Finding 1)

Item:Activity Equipment - Log WalkRisk Level:L - Low RiskManufacturer:Playground PeopleSurface:Woodchip







Action: Monitor for any further deterioration and replace as required

#### 6 - Low Risk (Finding 2)

Item: Activity Equipment - Log Walk Risk Level: Manufacturer: Playground People Surface:





Finding: The paintwork on this item has been damaged or Action: Treat any rusting components and repaint worn exposing the metal underneath which is rusting


L - Low Risk

Woodchip

#### 10 - Low Risk (Finding 1)

Item: Swings - Basket Swing - Type 1 Risk Level: L - Low Risk Playground People Surface: Woodchip Manufacturer:







Action: inspect and replace bolts, screws and or nails as required



Item:Rocking Equipment - Misc SpringerRisk Level:L - Low RiskManufacturer:Playground PeopleSurface:Woodchip





**Finding:** The paintwork on the spring has been damaged or **Action:** Treat any rusting components and repaint worn exposing the metal underneath which is rusting

#### 10 - Low Risk (Finding 1)

Item:Other - Cable RunwayRisk Level:L - Low RiskManufacturer:UnknownSurface:Compacted Earth





Finding: Protruding wires Action: Secure protrusion

# 6 - Low Risk (Finding 2)

Item: Other - Cable Runway Manufacturer: Unknown

Finding: We recommend that the main cable is thoroughly Action: Inspect cable every 24 months inspected at least once every 2 years this; will involve either removing the cable or gaining access by ladders and/or

steps to inspect for damage or internal rusting, this will help

to ensure the continued safe use of the equipment

Risk Level: L - Low Risk Surface: Compacted Earth



#### 20 - High Risk (Finding 3)

Other - Cable Runway Manufacturer: Unknown



Finding: The rocks forms a hard object within the falling space of the equipment in contravention of the requirements of NZ 5828:2015 Part 1





Action: Relocate runaway so not over the stream



### 12 - Moderate Risk (Finding 4)

Item: Other - Cable Runway
Manufacturer: Unknown

Risk Level: M - Moderate Risk Surface: Compacted Earth



Finding: Seat not secured on chain

Action: Secure seat so it cannot move up the chain



#### 10 - Low Risk (Finding 5)

Item: Other - Cable Runway



Risk Level: L - Low Risk Surface: Compacted Earth



**Finding:** An impact absorbing surface is recommended for **Action:** Provide an appropriate impact absorbing surface this item of equipment



Item: Other - Cable Runway

Manufacturer: Unknown



Finding: The chain openings are in excess of 8.6mm as recommended by NZ 5828:2015

Risk Level: V - Very Low Risk Surface: Compacted Earth



Action: Monitor use and replace with compliant chains when swings needs replacing