PAEKĀKĀRIKI COMMUNITY BOARD MATTERS UNDER ACTION As at 29 May 2018

	As at 29 May 2018 Matters Under Action									
ltem	Date Raised	Target Date	Matter	Responsible Officer	Action/Progress					
1.	29/1/2013	December 2017	Coastal protection upgrade	Coastal & Stormwater Asset Manager	Options for the replacement of the Seawall have been presented to Council for its consideration as part of the next LTP. The LTP proposal is for works to be funded in years 3-5 and from the maintenance fund in the interim. No change in situation.					
2.	2/6/2015	December 2017	Tilley Road flood protection	Coastal & Stormwater Asset Manager	The projects associated with Tilley Road flooding are in the Stormwater reprioritised work programme and become part of the next LTP depending on the funding approved by Council. Stormwater priorities in the LTP focused on habitable dwellings. No change in situation.					
3.	14/7/2015	February 2018	Village Parking options	Group Manager Infrastructure Services	The P120 parking area (top of Ames Street) continues to be monitored. Report to be presented by Council Officer at this meeting.					
4.	14/2/2017	February 2018	Beach Road parking	Group Manager Infrastructure Services	The Board preferred an education strategy ie. issuing fliers instead of enforcement notices, and the monitoring would continue. This is ongoing.					
5.	14/2/2017	June 2018	Village signage	Group Manager Infrastructure Services	Signage for the village was dependent on available funds this financial year. Waiting until track along SH1 is completed so that any signage includes the new Te Araroa route.					
6.	5/7/2016	March 2018	Minor traffic improvements	Group Manager Infrastructure Services	 This financial year's works programme included: Robertson/Wellington Roads - priority 					
					Work has been completed apart from some additional topsoiling and grass seed.					

	Matters Under Action								
ltem	Date Raised	Target Date	Matter	Responsible Officer	Action/Progress				
7.	5/7/2016	March 2018	Road Safety	Group Manager Infrastructure Services	 Ocean Road – broken yellow lines (byls) 				
					This needs further clarification and investigation by Council officers. If a serious safety issue is identified then byls will be installed. This is ongoing.				